

Certificate of Registration

QUALITY MANAGEMENT SYSTEM - ISO/TS 16949:2002

This is to certify that:

HellermannTyton
7930 Faulkner Road
Milwaukee
Wisconsin
53224
USA

Holds Certificate No: **TS 92382**

and operates a Quality Management System which complies with the requirements of ISO/TS 16949:2002 for the following scope:

Please see scope page.

For and on behalf of BSI:



President, BSI Management Systems America, Inc.

Originally Registered: **08/29/2008**

Latest Issue: **08/29/2008**

Expiry Date: **08/28/2011**

IATF Number: **0071563**



Page: 1 of 3



Management
Systems

This certificate remains the property of BSI and shall be returned immediately upon request.
An electronic certificate can be authenticated online. Printed copies can be validated at www.bsigroup.com/ClientDirectory
To be read in conjunction with the scope above or the attached appendix.
Further clarifications regarding the scope of this certificate and the applicability of ISO/TS16949:2002 requirements may be obtained by consulting the organization.

IATF Contracted Office: 12110 Sunset Hills Road, Suite 200, Reston, VA 20190, USA

Certificate No: TS 92382

Registered Scope:

The design, and manufacture of cable care management products that include injection molded fasteners and cable ties.

Permitted Exclusions: None

Including the following remote support functions:

Hellermann Tyton
1115 Hosler Drive
Bolingbrook, IL. 60440
Distribution

Hellermann-Tyton
8475 N. 87th Street
Milwaukee, MI 53224
Purchasing, Packaging

Originally Registered: **08/29/2008**

Latest Issue: **08/29/2008**

Expiry Date: **08/28/2011**

IATF Number: 0071563

Page: 2 of 3

This certificate remains the property of BSI and shall be returned immediately upon request.

An electronic certificate can be authenticated [online](http://www.bsigroup.com/ClientDirectory). Printed copies can be validated at www.bsigroup.com/ClientDirectory

To be read in conjunction with the scope above or the attached appendix.

Further clarifications regarding the scope of this certificate and the applicability of ISO/TS16949:2002 requirements may be obtained by consulting the organization.

IATF Contracted Office: 12110 Sunset Hills Road, Suite 200, Reston, VA 20190, USA

Certificate No: **TS 92382**

Location

Registered Activities

HellermannTyton
7930 Faulkner Road
Milwaukee
Wisconsin
53224
USA

The design, and manufacture of cable care management products that include injection molded fasteners and cable ties.

Originally Registered: **08/29/2008**

Latest Issue: **08/29/2008**

Expiry Date: **08/28/2011**

IATF Number: 0071563

Page: 3 of 3

This certificate remains the property of BSI and shall be returned immediately upon request.
An electronic certificate can be authenticated online. Printed copies can be validated at www.bsigroup.com/ClientDirectory
To be read in conjunction with the scope above or the attached appendix.
Further clarifications regarding the scope of this certificate and the applicability of ISO/TS16949:2002 requirements may be obtained by consulting the organization.

IATF Contracted Office: 12110 Sunset Hills Road, Suite 200, Reston, VA 20190, USA

Certificate of Registration

QUALITY MANAGEMENT SYSTEM - ISO 9001:2000

This is to certify that:

HellermannTyton
7930 Faulkner Road
Milwaukee
Wisconsin
53224
USA

Holds Certificate No: **FM 503384**

and operates a Quality Management System which complies with the requirements of ISO 9001:2000 for the following scope:

The design, manufacture and distribution of cable care management products (molded fasteners and cable ties), network cabling products, wiring duct and raceway, and identification systems products.

For and on behalf of BSI:



President, BSI Management Systems America, Inc.

Originally Registered: **12/02/2005**

Latest Issue: **09/29/2008**

Expiry Date: **09/28/2011**



Page: 1 of 1

BSI
BSI
Management
Systems

This certificate remains the property of BSI and shall be returned immediately upon request.
An electronic certificate can be authenticated online. Printed copies can be validated at www.bsigroup.com/ClientDirectory
To be read in conjunction with the scope above or the attached appendix.
Americas Headquarters: 12110 Sunset Hills Road, Suite 200, Reston, VA 20190, USA.